


PI 1762

For technical personnel only!

1/1

PRODUCT INFORMATION

THROTTLE VALVE 7.03703.38.0/39.0

DIFFERENCE: VACUUM CONNECTION

The two throttle valves 7.03703.38.0 and 7.03703.39.0 are identical technically. The throttle valve 7.03703.38.0 also has a vacuum connection. Competitors and vehicle manufacturers (OE) only offer the version with vacuum connection (036 133 062 L, 408-238-321-006Z). Depending on the vehicle (see table), you may have to seal the vacuum connection with an additional rubber cap and a hose clamp (only available from OE).



Throttle valve
7.03703.38.0 with
vacuum connection

MOTORSERVICE STILL OFFERS BOTH VERSIONS.

ADVANTAGES:

- no sealing of the vacuum connection required
- no potential leakage
- no additional components need to be purchased from OE



Throttle valve
7.03703.39.0
without vacuum
connection



NOTE:

Please note the exact distinction according to chassis number, engine ID code and model year.

The throttle valves must be “taught in” after installation. Always observe the instructions given by the vehicle manufacturer.

Suitable for	Model	Pierburg no.	Replacement for	Ref. no.*
Seat	Leon/Toledo II 1.4	7.03703.38.0	7.03703.01.0	036 133 062 L
Škoda	Octavia I 1.4			408-238-321-006Z
Volkswagen	New Beetle/Bora/Golf IV/Golf V 1.4			
Audi	A2 1.4	7.03703.39.0	7.03703.09.0	036 133 062 B
Seat	Cordoba 1.2/1.4; Ibiza IV 1.2; Ibiza III/IV 1.4, Inca 1.4			036 133 062 N
Škoda	Fabia I 1.2/1.4			408-238-321-007Z
Volkswagen	Polo 1.2/1.4, Caddy II 1.4, Lupo 1.4			

* The reference numbers given are for comparison purposes only and must not be used on invoices to the consumer.

OUR **HEART** BEATS FOR YOUR ENGINE.