



TB1305

LuK Service Info

Part Nr. 500 0217 40 – PTO / RELEASE BRG

Manufacturer: LANDINI, MASSEY

Model: LANDINI – 10000, 12500, 13000 & 14500

MASSEY – 1014, 1024, 1114 & 1134

Art.-Nr.: 500 0217 40

New product / Neues Produkt /
Produit Nouveau / Nuevo Producto
/ Nuovo Prodotto



631 3161 10 = 231 0030 10 + 331 0097 16 + 500 0587 10 + 500 0217 40 + 410 0154 40

633 0523 10 = 233 0020 12 + 333 0019 16 + 500 0587 10 + 500 0217 40 + 410 0154 40



500 0217 40
OE 392191X1

Call : +44 (0) 1432 264264
vehicelifetimesolutions.schaeffler.com

SCHAEFFLER
REP>XPERT