

NEW PRODUCT HIGHLIGHT | JAN2019



Blue Print ADS76908

to fit:
Subaru Forester, Legacy, Outback,
XV Models 2.0 Diesel

EN



CHARGER INTAKE HOSE FOR TURBOCHARGER

Function

Induction hose from intercooler to inlet manifold.

Failure

The hose splits, causing unmetered air to leak.
This can cause loss of engine power and increased fuel consumption.

For more technical information please visit: partsfinder.bilsteingroup.com